

# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION III

## 1650 Arch Street Philadelphia, Pennsylvania 19103-2029

**SUBJECT:** BGF Industries, Inc. 30-Day Notification Request

**FROM:** James J. Burke, Director

Waste and Chemicals Management Division (3WC00)

**TO:** Bradley M. Campbell

Regional Administrator (3RA00)

### **Recommended Action:**

Please sign the attached letter responding to BGF Industries Inc's (BGF) 30-day notification of intent to decontaminate localized areas of PCB contamination on the Unit #2 Dryer Platform and from a brick wall in a metal fabrication shed at their facility in Altavista, Virginia. U.S. EPA Region III's PCB Program is requesting that a brief summary of the cleanup activities be submitted upon completion.

The notification from BGF provides for cleanup in accordance with 40 C.F.R. § 761.61(a) and includes the information required by the regulations at 40 C.F.R. § 761.61(a)(3)(i)(A) - (E).

## **Background:**

BGF's Altavista plant ("Site"), located at 401 Amherst Avenue in Altavista, Virginia, consists of two main buildings and three parking areas. The buildings and parking areas occupy approximately 22 acres. The facility primarily performs fiberglass cloth slashing. PCB oil, used by the former owner (Burlington Industries), was used in a heat-transfer drying system at the facility from the early 1960's until approximately 1973. A brick wall in a metal fabrication shed attached to the main facility building, as well as a unit dryer platform, were contaminated with PCBs due to multiple pump and gasket failures on the heat-transfer system. Adjacent properties consist of an industrial facility and residential areas. The Site is bordered by Norfolk and Southern Railroad tracks and Lane Furniture Company property to the south and residential areas to the north, east and west. The Staunton River is located approximately 600 feet to the southeast. The facility is maintained by 24-hour security.

## **State/Regional Coordination:**

Customer Service Hotline: 1-800-438-2474

A copy of BGF's letter, dated August 22, 2000 and Region III's response will be forwarded to Dr. Khizar Wasti, Virginia Department of Health, and Erica Dameron, Virginia Department of Environmental Quality, Superfund Program Coordinator.

# **Anticipated Impacts:**

None

Customer Service Hotline: 1-800-438-2474

**SUBJECT:** BGF Industries, Inc. 30-Day Notification Request

**FROM:** James J. Burke, Director

Waste and Chemicals Management Division (3WC00)

**TO:** Bradley M. Campbell

Regional Administrator (3RA00)

### **Recommended Action:**

Please sign the attached letter responding to BGF Industries Inc's (BGF) 30-day notification of intent to decontaminate localized areas of PCB contamination on the Unit #2 Dryer Platform and from a brick wall in a metal fabrication shed at their facility in Altavista, Virginia. U.S. EPA Region III's PCB Program is requesting that a brief summary of the cleanup activities be submitted upon completion.

The notification from BGF provides for cleanup in accordance with 40 C.F.R. § 761.61(a) and includes the information required by the regulations at 40 C.F.R. § 761.61(a)(3)(i)(A) - (E).

## **Background:**

BGF's Altavista plant ("Site"), located at 401 Amherst Avenue in Altavista, Virginia, consists of two main buildings and three parking areas. The buildings and parking areas occupy approximately 22 acres. The facility primarily performs fiberglass cloth slashing. PCB oil, used by the former owner (Burlington Industries), was used in a heat-transfer drying system at the facility from the early 1960's until approximately 1973. A brick wall in a metal fabrication shed attached to the main facility building, as well as a unit dryer platform, were contaminated with PCBs due to multiple pump and gasket failures on the heat-transfer system. Adjacent properties consist of an industrial facility and residential areas. The Site is bordered by Norfolk and Southern Railroad tracks and Lane Furniture Company property to the south and residential areas to the north, east and west. The Staunton River is located approximately 600 feet to the southeast. The facility is maintained by 24-hour security.

## **State/Regional Coordination:**

A copy of BGF's letter, dated August 22, 2000 and Region III's response will be forwarded to Dr. Khizar Wasti, Virginia Department of Health, and Erica Dameron, Virginia Department of Environmental Quality, Superfund Program Coordinator.

#### **Anticipated Impacts:**

None

Customer Service Hotline: 1-800-438-2474

CONCURRENCES								
SYMBOL•	3WC33	3WC33	3WC33	3WC33	3WC30			
SURNAM E	Originato r	Creamer	Andrelczy k	Dickens	Webb			
DATE •								